




STATE OF NEVADA  
 COMMISSION ON MINERAL RESOURCES  
**DIVISION OF MINERALS**  
 400 W. King Street, Suite 106  
 Carson City, Nevada 89703  
 (775) 684-7040 • Fax (775) 684-7052  
<http://minerals.nv.gov/>



STEVE SISOLAK  
 Governor

Las Vegas Office: 2030 E. Flamingo Rd. #220, Las Vegas, NV 89119  
 Phone: (702) 486-4343; Fax: (702) 486-4345

RICHARD PERRY  
 Administrator

January 31, 2019

Re: Securing of Hazardous Abandoned Mine Feature(s)

Dear Claimant/Property Owner:

The Division of Minerals' Abandoned Mine Lands Program is continuing its legislatively-mandated task of discovering dangerous conditions that result from mining practices that took place at mines that are no longer in operation. Generally, after the discovery of an unsecured dangerous condition, the claimant/owner is notified by the Division that it is their responsibility to secure the hazard. However, when the Division determines that the hazard represents an imminent public safety risk, the Division may proactively secure the hazard prior to formal notification to the claimant/owner or the occurrence of any securing efforts by the claimant/owner, or when a previously secured site is found in disrepair.

Recently, Division staff, its contractor(s) or volunteers working on behalf of the Division *have secured* one or more hazards on land believed to be on your claim or parcel. This effort was performed solely to protect the public from imminent physical safety hazard(s).

This letter is intended to provide you with notice of these efforts and serves as a reminder that if the hazard(s) are on your active claim or private parcel, then any maintenance or future securing work is your responsibility.

Enclosed please find a copy of our hazard inventory sheet(s) detailing the location and description of the hazard(s) and securing status. If you have any questions regarding the hazard(s) or the recent work, please do not hesitate to contact this office.

Sincerely,

Robert Ghiglieri  
 Chief, Abandoned Mine Lands Program  
 Nevada Division of Minerals  
 775-684-7048  
[rghiglieri@minerals.nv.gov](mailto:rghiglieri@minerals.nv.gov)



State of Nevada  
Commission on Mineral Resources  
Division of Minerals



### Listing of Hazards Notification

**WATSON CHARLES**  
**PO BOX 1956**  
**CHESTER, CA 96020-1956**

Hazard ID	Topo Sheet	Township	Range	Section	Q Section	Land Status	Haz. Rank	Curr. Securing Method
ES-3340	Gold Point	07S	41.5E	26	NWSE	Bur. of Land Mgmt.	8	ENCLASURE/FENCE
ES-3341	Gold Point	07S	41.5E	26	NWSE	Bur. of Land Mgmt.	8	ENCLASURE/FENCE

**Total Number of Sites: 2**



## Abandoned Mine Hazard Inventory Sheet

**County:** Esmeralda  
**Hazard ID:** ES-3340  
**Date Investigated:** 6/26/2018  
**Investigated By:** Mesa2  
**Ownership Research Date:** 11/27/2018  
**Research By:** DAS  
**Visitation Signs:** No  
**Topo. Sheet:** Gold Point  
**Accessibility:** Easy  
**Field Office:** BM  
**Township:** 07S  
**Section:** 26  
**UTM NAD83 E:** 469836  
**GPS Acc. (ft):**  
**GPS Elev. (ft):** 0  
**Waste Rock:** Yes  
**Water Present:** No  
**Water/Chemical Description:**  
**All Mine Visible:** Yes  
**Cribbing or Timbers:** No  
**Bat:** 0  
**Tortoise:** 0  
**Wildlife Notes:**  
**Cultural Resources:**  
**Claim/Mine Name:**  
**Assessor Parcel Num.:**  
**Mineral Survey:**  
**NV Mining Claim:**

**Degree of Hazard (per NAC 513)**  
**Hazard Location:** 5  
**Hazard Degree:** 3  
**Hazard Rank:** 8-High  
**Hazard Type:** SHAFT  
  
**Land Status:** BLM  
**Dist to Road (ft):** 100  
  
**Range:** 41.5E  
**QQ Section:** NWSE  
**UTM NAD83 N:** 4128500

**GPS or Topo:** Field Topo QC  
**Size Estimate (yd3):** 50  
**Chem. Toxicity:** No  
  
**Crevices:** No  
**Detectable Airflow:** No  
**Owl:** 0  
**Other:** 0

Name	Co Attn	Street / PO Box	City State Zip Country
WATSON CHARLES		PO BOX 1956	CHESTER, CA, 96020-1956,

**Owner Notif. Date:**

**Owner Resp. Date:**

**County Notif. Date:**

**Fld. Off. Notif. Date:**

**BLM Approv. Date:**

**Hazard Description:** Shaft. 4' x 3' collar. 12' deep. Connecting to ES-3341. Near road and prospect pits, difficult to see upon approach.

Visit Date	By	Sec. Method	Action Taken	Documentation
6/27/2018	Mesa7	EN	BFN	
6/26/2018	Mesa2	NS	NDS	



## Abandoned Mine Hazard Inventory Sheet

**County:** Esmeralda  
**Hazard ID:** ES-3341  
**Date Investigated:** 6/26/2018  
**Investigated By:** Mesa7  
**Ownership Research Date:** 11/27/2018  
**Research By:** DAS  
**Visitation Signs:** No  
**Topo. Sheet:** Gold Point  
**Accessibility:** Easy  
**Field Office:** BM  
**Township:** 07S  
**Section:** 26  
**UTM NAD83 E:** 469901  
**GPS Acc. (ft):**  
**GPS Elev. (ft):** 0  
**Waste Rock:** Yes  
**Water Present:** No  
**Water/Chemical Description:**  
**All Mine Visible:** No  
**Cribbing or Timbers:** No  
**Bat:** 1  
**Tortoise:** 0  
**Wildlife Notes:**  
**Cultural Resources:**  
**Claim/Mine Name:**  
**Assessor Parcel Num.:**  
**Mineral Survey:**  
**NV Mining Claim:**

**Degree of Hazard (per NAC 513)**  
**Hazard Location:** 5  
**Hazard Degree:** 3  
**Hazard Rank:** 8-High  
**Hazard Type:** DECLINE

**Land Status:** BLM  
**Dist to Road (ft):** 60

**Range:** 41.5E  
**QQ Section:** NWSE  
**UTM NAD83 N:** 4128473

**GPS or Topo:** Field Topo QC  
**Size Estimate (yd3):** 60  
**Chem. Toxicity:** No

**Crevices:** Yes  
**Detectable Airflow:** No  
**Owl:** 0  
**Other:** 0

Name	Co Attn	Street / PO Box	City State Zip Country
WATSON CHARLES		PO BOX 1956	CHESTER, CA, 96020-1956,

**Owner Notif. Date:**

**Owner Resp. Date:**

**County Notif. Date:**

**Fld. Off. Notif. Date:**

**BLM Approv. Date:**

**Hazard Description:** Decline. Large opening that then leads down 5' to decline. Decline portal is 3'by3' with unknown length. 10' in the decline connects to shaft ES-3340.

Visit Date	By	Sec. Method	Action Taken	Documentation
6/27/2018	Mesa7	EN	BFN	
6/26/2018	Mesa7	NS	NDS	